


CORNER RECORD

COUNTY OF PLACER, CALIFORNIA

City of _____

Document Number 20150021

Brief Legal Description 9-RS-21 O.R.P.C.



SEC 7
T13N
R9E

CORNER TYPE

Government Cor. Control
Meander Property
Rancho other
Date of Survey MARCH 12, 2015

CORNER TYPE (optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner - Left as Found Found and Tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner: FOUND RAILROAD SPIKE IN TRAVELED WAY OF MEADOW GATE ROAD AS SHOWN ON RECORD OF SURVEY NO.954, AT BOOK 9, PAGE 21, O.R.P.C., FROM FOUND MONUMENT, ESTABLISHED REFERENCE POINTS PRIOR TO ASPHALT OVERLAY.

A description of the physical condition of the monument as found and as set or reset: FROM REFERENCE POINTS, SET PK-NAIL W/ 1-1/4" BRASS TAG STAMPED "PLACER CO. SURVEYOR" CENTERED OVER THE FOUND MONUMENT AFTER ASPHALT OVERLAY.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on JULY 30 2015.

Signed [Signature] L.S. or R.C.E. Number LS 7941



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ 20 ____ and examined and filed August 12, 2015 20__.

Signed [Signature] Title County Surveyor




County Surveyor's Comment:
xx

BOOK 18 OF CORNER RECORDS, PAGE 17

9-RS-21



SCALE 1"=30'



LEGEND

- ⊗ FD. RAIL ROAD SPIKE AS SHOWN ON 9-RS-21, PRIOR TO PAVEMENT OVERLAY, SET PK NAIL WITH "PLACER CO. SURVEYOR" TAG
- SET PK NAIL WITH "PLACER CO. SURVEYOR" TAG
- ⊙ SET 5/8" REBAR WITH "PLACER CO. SURVEYOR" TAG
- () RECORD PER 9-RS-21

NOTE

THIS CORNER RECORD REPRESENTS THE AS FOUND LOCATION OF THE MONUMENTS SHOWN HEREON, NO SURVEY HAS BEEN MADE OF SAID MONUMENTS IN RELATIONSHIP TO REFERENCED RECORD MAPS.