


CORNER RECORD

COUNTY OF PLACER, CALIFORNIA

City of UNINCORPORATED AREA

Document Number 20150056

Brief Legal Description LOT 14 SERENE LAKES UNIT #1
BOOK "I" OF MAPS PAGE 17 P.C.O.R.



SEC. 34
T. 17 N.
R. 14 E.
M.D.M.

CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 6/30/15

COORDINATES (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner:

- = FOUND 3/4" REBAR w/ TAG L.S. 3229 PER 4/SUR/1 P.C.O.R.
- ' = FOUND 1/2" REBAR PER 4/SUR/1 P.C.O.R., TAG MISSING
- ⊗ = FOUND 1" IRON PIPE w/ PLASTIC PLUG L.S. 5549
- = FOUND 3/4" IRON PIPE w/ PLASTIC PLUG L.S. 5549 PER 7/CR/41

A description of the physical condition of the monument as found and as set or reset:

○ = SET BATHEY MONUMENT (T-BAR) w/ NAIL & TAG P.L.S. 8628

JN: 15054

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land

Surveyors' Act on JULY 6, 2015.


Signed [Signature] L.S. or R.C.E. Number 8628
LIC. EXPIRES 12/31/15

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ 20 _____ and examined

and filed September 8 2015.

Signed [Signature] Title County Surveyor



County Surveyor's Comment _____

BOOK 18 CORNER RECORDS PAGE 32

NOTE: THE BEARINGS AND DISTANCES SHOWN ARE RECORD PER "I/MAPS/17 P.C.D.R. AND PER 4/SUR/1 P.C.D.R. NO MATERIAL DISCREPANCIES WITH RECORD INFORMATION WERE FOUND.

