


(For County Use Only)

CORNER RECORD

COUNTY OF PLACER T. 15N R. 11E MDM MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION — DATE OF VISIT _____ 19____
COR 13 of MS 1397 Mountain Gate P.H.



CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

COR 13
MGPM
LS3062
1973

Found $\frac{3}{4}$ " Brass Capped pipe per ROS 5/10/02
A 48" DOUGLAS FIR SNAG BEARS $S22^{\circ}45'W - 2.64'$ (ORIG PT)

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED


Marked B.T.'S as follows:
A 6" Black oak bears $S09^{\circ}15'W - 7.9'$ "MS 1397 BT"
A 6" Black oak bears $N75^{\circ}12'E - 25.3'$ "MS 1397 BT"

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

(Fold)

SEE CONTROL DIAGRAM ON FILE WITH USFS, NEVADA CITY,
DAMASCUS CADASTRAL SURVEY - CONTRACT NO. 53-9A63-2-IT56

SKETCH: (Include reference tie or witness points, remarks and topo of area)



NOTE: DISTANCES TO B.T.'S WERE
MEASURED TO A NAIL IN NOTCH
NEAR BASE OF TREE TRUNK

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY
DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT

NO 3062 SIGNED: Emerson Smith
L.S. or R.C.E. No. LS3062

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____
AND EXAMINED AND FILED 12/16 1992
BY: David M. Daniel
TITLE: DEPUTY COUNTY SURVEYOR

DOCUMENT No. _____

STATEMENT ON BACK OF SHEET

YES NO

Book 3, Corner Records, Page 100

