


CORNER RECORD

Document Number _____

City of _____ County of PLACER, California

Brief Legal Description LOTS 20 & 21 MOXNA BEACH SUBDIVISION - H/MAPS/7

T. 14N. R. 17E. M.D.M.



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 11/5/92

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

- ① INDICATES FOUND 1/2" REBAR NO TAG.
 - ② INDICATES FOUND 3/4" REBAR NO TAG. HELD FOR LINE
 - ③ INDICATES FOUND 2" IRON PIPE. NO TAG. HELD FOR LINE
 - ④ INDICATES CALCULATED POSITION NOTHING FOUND OR SET.
 - ⑤ INDICATES FOUND 3/4" IRON PIPE NO TAG
 - ⑥ INDICATES FOUND 1" IRON PIPE NO TAG
- A description of the physical condition of the monument as found and as set or reset:
- ⑦ SET 5/8" REBAR W/ CAP LS 6460.
 - ⑧ SET FK NAIL & TAG (LS 6460) IN ASPHALT DRIVE
 - ⑨ SET 10" X 3/8" SPIKE W/ CAP IN STUMP (LS 6460.)

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on 11/11/92 19____.

Signed [Signature] L.S. or R.C.E. Number LS 6460



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 11/13 1992 and examined and filed 1/4 1993.

Signed [Signature] Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____

Book 3, Corner Records, Page 121

