


# CORNER RECORD

COUNTY OF PLACER T. 14 N R. 13 E MD MERIDIAN CALIFORNIA

CORNER TYPE: GOVT. CORNER  MEANDER  RANCHO  CONTROL  OTHER

CORNER IDENTIFICATION — DATE OF VISIT July 17 1989



S21	S22
S28	S27

GLO BRASS CAP

CORNER — LEFT AS FOUND  FOUND AND TAGGED  REESTABLISHED OBLITERATED CORNER  REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH  
 FOUND 2" IP, in rock mound 40" dia. by 12" high, WITH STD GLO BRASS CAP STAMPED:  
 FROM WHICH BEARS:


- PP 35" DBH, N63°E, 34.9', healed scar. (GLO) YP 30" N 64¼°E, 35.0'
- BO 24" DBH, S37°E, 62.5', healed scar. (GLO) OAK 22", S37½°E, 64.7'
- PP 64" DBH, S4°W, 80.5', healed scar. (GLO) YP 60", S3½°W, 79.2'
- BO 10" DBH, N87°W, 55.4', healed scar. (GLO) OAK 14", N87°W, 55.4'

T14 N	R13 E
S21	S22
S28	S27
1926	

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST  SECOND  THIRD   
 STATIONS USED: NGS (USC & GS)  STATE  COUNTY  OTHER  STATION \_\_\_\_\_ STATION \_\_\_\_\_  
 ZONE \_\_\_\_\_ ELEVATION \_\_\_\_\_ NORTHINGS (Y) \_\_\_\_\_ EASTINGS (X) \_\_\_\_\_

SKETCH: (Include reference tie or witness points, remarks and topo of area)



BOOK 2, CORNER RECORDS, PAGE 1  
 BOOK 3, CORNER RECORDS PAGE 156



**SURVEYOR'S CERTIFICATE**

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY  
 SUPERVISION IN CONFORMANCE WITH THE LAND SURVEYORS ACT  
September 5 1989

SIGNED: James F. Micklos  
 L.S. No. LS 3848

SEAL

**COUNTY SURVEYOR'S CERTIFICATE**

THE CORNER RECORD WAS RECEIVED 9/11 1989  
 AND EXAMINED AND FILED 10/27 1989

BY: Deputy Surveyor  
 TITLE: DEPUTY COUNTY SURVEYOR

DOCUMENT No. \_\_\_\_\_

STATEMENT ON BACK OF SHEET

YES  NO