


CORNER RECORD

COUNTY OF PLACER, CALIFORNIA

City of _____ Document Number _____

Brief Legal Description LOT 41, CHAMBERLANDS UNIT A, BOOK "F", PAGE 33



T 14 N
R 17 E

CORNER TYPE

COORDINATES
(Optional)

Government Corner Control N. _____
Meander Property E. _____
Rancho Other Zone _____ Datum _____
Date of Survey _____ Elev. _____

Corner— Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner:

● FOUND 5/8" REBAR, UNLESS OTHERWISE NOTED

A description of the physical condition of the monument as found and as set or reset:

∅ SET 5/8" REBAR W/ 2" CAP STAMPED
TAHOE BASIN LAND SURVEYING, L.S. 5886

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land

Surveyor's Act on 6-19 2000

Signed [Signature] L.S. or R.C.E. Number L.S. 5886



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received October 1, 19 98 and examined

and filed August 23, 19 2000

Signed [Signature] Title Deputy Co. Surveyor



County Surveyor's Comment _____



BOOK 6 CORNER RECORDS PAGE 68

J.N. 9856 CRD, COR9856 PL

FOUND BENT
(SHOT AT SPIN)



SCALE 1" = 50'

() DENOTES RECORD & MEASURED
AS PER "F"-33