

CORNER RECORD

COUNTY OF PLACER, CALIFORNIA

City of _____ Document Number _____

Brief Legal Description WALDEN WOODS UNIT 2 & 3 BOOK L MAPS PAGE 4



TUN-R7E

CORNER TYPE

COORDINATES (Optional)

- Government Corner
- Meander
- Rancho
- Date of Survey _____
- Control
- Property
- Other

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner:

FO 5/8" REBAR, NO TAG, AT THE NE COR LOT 54, SE COR LOT 102, AND THE NW COR LOT 70

A description of the physical condition of the monument as found and as set or reset:


SET 3/4" REBAR AT SE COR LOT 54, TAGGED PL. G. SURVEYOR

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land

Surveyors' Act on MAY 31 192000

Signed John H. Rietjens L.S. or R.C.E. Number LS4323




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received June 1, 192000 and examined

and filed June 5, 192000

Signed Wesley Snyder Title Deputy Co. Surveyor



County Surveyor's Comment _____

BOOK 6 CORNER RECORDS PAGE 66

