

# CORNER RECORD

Document Number \_\_\_\_\_

City of \_\_\_\_\_

County of Placer, California

Brief Legal Description Lot 26 Serene Lakes Unit No 1  
Book I of maps Page 17



T. 17N  
R. 14E  
M.D.M.

### CORNER TYPE

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey 11/19/93

### COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

● = FOUND 1/2" REBAR PER BOOK I/MAPS/17  
 ● = FOUND 1/2" REBAR W/TAG STAMPED L.S. 3229

A description of the physical condition of the monument as found and as set or reset:


○ = SET 3/4" IRON PIPE W/PLASTIC PLUG STAMPED L.S. 5549

JM 93131

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on DEC. 13 1993.

Signed Charles R. Sage Jr. L.S. or R.C.E. Number L.S. 5549  
LIC. EXP. 6-30-97




### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JUNE 14 1994 and examined


and filed 7/20 1994.

Signed John Rietjens Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment \_\_\_\_\_



BOOK 4 CORNER RECORDS PAGE 52



NOTE: BEARINGS & DISTANCES SHOWN ARE RECORD PER I/MAPS/17. NO MATERIAL DESCREANCIES WITH RECORD INFORMATION WERE FOUND.