


CORNER RECORD

Document Number _____

City of _____

County of Placer, California

Brief Legal Description Lot 179 Dollar Point Unit #3
Book H of Subd. Page 5



T.16 N
R.17 E
M.D.M.

CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 5-4-94

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

- = FOUND 1/2" REBAR, NO TAG
- = FOUND 5/8" REBAR W/ PLASTIC CAP, STAMPED L.S. 3422
- ⊗ = FOUND CHISEL "X" ON ROCK

A description of the physical condition of the monument as found and as set or reset:

- = SET 3/4" IRON PIPE W/ PLASTIC PLUG, STAMPED L.S. 5549

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on MAY 5 1994.

Signed Charles R. Sage Jr. L.S. or R.C.E. Number L.S. 5549
LIC. EXP. 6-30-97



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JUNE 14 1994 and examined and filed 7/20 1994.

Signed John Ruben Title DEPUTY COUNTY SURVEYOR




County Surveyor's Comment _____

BOOK 4 CORNER RECORDS PAGE 53

Scale

1" = 80'



Note: Bearings and distances shown are Record per H/Sub/5.
 No material discrepancies with Record Information were found.