


# CORNER RECORD

Document Number \_\_\_\_\_

City of \_\_\_\_\_ County of Placer, California

Brief Legal Description Lot 89 Serene Lakes Unit #1  
Book 1 of Maps Page 17



T.17N  
R.14E.  
MDM

### CORNER TYPE

- Government Corner
- Control
- Meander
- Property
- Rancho
- Other
- Date of Survey 7/1/94

### COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

- = Found 5/8" rebar w/ tag 3329
- = Found 1/2" rebar per I/MAPS/17

A description of the physical condition of the monument as found and as set or reset:

- = Set 3/4" iron pipe w/ plastic cap stamped LS 5549

JN:9493

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on JULY 13 1994.


Signed Charles R. Sage Jr. L.S. or R.C.E. Number L.S. 5549  
LIC. EXP. 6-30-97



### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received SEPT 12 1994 and examined and filed 9/16 1994.

Signed John Rietjens Title DEPUTY Co. SURVEYOR




County Surveyor's Comment \_\_\_\_\_

BOOK 4 CORNER RECORDS PAGE 69

Scale:



1" = 80'



BOOK 4 CORNER RECORDS PAGE 69

Note: Bearing + distances shown are Record per I/MAPS 17.  
No material discrepancies with Record Information were found.