


CORNER RECORD

Document Number _____

City of _____

County of Placer, California

Brief Legal Description Lot 24 Tahoe Sierra Estates
Book F of Maps Page 4



T.15N
R.17E
M.D.M.

CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 9-26-94

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

● = Found 1/2" rebar per F/Maps/4.
 ● = Found 3/4" rebar per F/Maps/4.

A description of the physical condition of the monument as found and as set or reset:


○ = Set 3/4" iron pipe w/ plastic plug, stamped L.S. 5549

94150

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on 9/30 19 94

Signed Charles R. Sage L.S. or R.C.E. Number L.S. 5549
LIC. EXP. 6-30-97



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received OCT 13 19 94 and examined and filed OCTOBER 14 19 94.


Signed John Rietjens Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____

BOOK 4 CORNER RECORDS PAGE 70

Scale: 1" = 100'



Note: Bearings and distances shown are Record per F/Maps/4.
 No material discrepancies with Record Information were found.

BOOK 4 CORNER RECORDS PAGE 70