


CORNER RECORD

Document Number _____

City of _____ County of Placer, California
Lot 183, Folsom Lake Estates Unit No. 2-C (M-29)
Brief Legal Description _____



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 7/11/2006

COORDINATES (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found centerline monuments per M-29.

A description of the physical condition of the monument as found and as set or reset: _____
From found CL mounts and found monuments at the southerly and westerly corners,
I reset the front corners, using 5/8" iron rods capped PLS 4327.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyors' Act on 7/18 19 2006


Signed Gary K. Sheldon L.S. or R.C.E. Number 4327



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 08-14-07 19 and examined
and filed SEPTEMBER 1 19 2007

Signed Charles B. Grant Title DEPUTY COUNTY
LS 6158 SURVEYOR



County Surveyor's Comment _____

BOOK 10 CORNER RECORDS PAGE 84

