


CORNER RECORD

Document Number _____

City of LINCOLN

County of PLACER, California

Brief Legal Description REFERENCE CORNERS, LOT 40/41, 57/58 BK "W" PG. 11



S. 17
T. 12N
R. 6E

CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey JUNE 2006

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner S Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
RESET REFERENCE CORNERS TO PROPERTY CORNERS, 1 FOOT INTO THE RIGHT OF WAY, ORIGINAL CORNERS WERE DESTROYED W/SIDEWALK REMOVAL

A description of the physical condition of the monument as found and as set or reset:
MISSING REFERENCE CORNERS WERE RE SET WITH PK NAIL AND LS TAG #3475 FLUSH INTO SIDEWALK WITH EPOXY PER CITY OF LINCOLN STANDARD DRAWING "H-26"

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on JULY 2006

Signed William E Mitchell P.L.S or R.C.E. No. LS 3475



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received 10-16-07

and examined and filed OCT 18 2007

Signed Charles B. Grant P.L.S or R.C.E. No. 6158

Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____



BOOK 10 CORNER RECORDS PAGE 96

FD. 3/4" RBLS6584
FD. 3/4" RBLS6584
SET PX NAIL W/LS TAG # 3475
PER CITY OF LINCOLN STD. DWG. "H-26"

FD. BRASS TAG W/LS TAG # 6584

