


CORNER RECORD

COUNTY OF PLACER, CALIFORNIA

City of \_\_\_\_\_ Document Number \_\_\_\_\_

Brief Legal Description BOOK 1. CORNER RECORDS. PAGE 31



S 1/2  
Sec. 2  
T. 11 N.  
R. 7 E.  
M.D.M.

CORNER TYPE

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey MAY 2, 05

COORDINATES  
(Optional)

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ Datum \_\_\_\_\_  
Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner:

FOUND COPPERWELD STAMPED for S. 1/4 Cor. Sec. 2, L.S. 3798, 1977 IN  
INTERSECTION OF KING Rd. and VAL VERDE Rd. Per BOOK 1, CORNER  
RECORDS. PAGE 31, FROM FOUND MONUMENT ESTABLISHED REFERENCE  
POINTS PRIOR TO ASPHALT OVERLAY.

A description of the physical condition of the monument as found and as set or reset:

FROM REFERENCE POINTS SET MAG NAIL w/ 1/4" BRASS WASHER  
STAMPED "PLACER CO SURVEYOR" CENTERED OVER FOUND MONUMENT  
AFTER ASPHALT OVERLAY

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on DECEMBER 20 2005.

Signed [Signature] L.S. or R.C.E. Number L.S. 7887



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received DEC. 22 2005 and examined and filed JAN. 5 2006.


Signed Charles B. Grant L.S. 6158 Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment \_\_\_\_\_

BOOK 10 CORNER RECORDS PAGE 42

FOUND COPPER WELD STAMPED  
FOR SOUTH QUARTER CORNER  
SECTION 2, L.S. 3798, 1977, SET  
MAG NAIL W/ 1-1/4" BRASS WASHER  
STAMPED "PLACER CO SURVEYOR"



NOT TO SCALE

BOOK 1, CORNER RECORDS, PAGE 31