


**CORNER RECORD**

Document Number \_\_\_\_\_

City of UNINCORPORATED AREA County of PLACER, California

Brief Legal Description LOTS 76+77 SERENE LAKES UNIT #2  
BOOK "I" OF MAPS PAGE 18 P.C.R.



SEC. 27  
T. 17N.  
R. 14E.  
M.D.M.

**CORNER TYPE**

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey 8/23/05

**COORDINATES (Optional)**

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

● = FOUND 1/2" REBAR, NO TAG, BELIEVE TO BE ORIGINAL PER I/MAPS/18  
● = FOUND 3/4" REBAR W/ NAIL + TAG, L.S. 3229

A description of the physical condition of the monument as found and as set or reset:


Ø = SET 1" IRON PIPE W/ PLASTIC PLUG, L.S. 5549

Wk. 05105

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on AUGUST 24 2005

Signed Charles R. Sage P.L.S or R.C.E. No. L.S. 5549  
LIC. EXP. 6/30/07



**COUNTY SURVEYOR'S STATEMENT**


This Corner Record was received \_\_\_\_\_

and examined and filed Nov 7 2006

Signed Charles B. Grant P.L.S or R.C.E. No. LS 6158


Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment \_\_\_\_\_



BOOK 10 CORNER RECORDS PAGE 62

NOTE: THE BEARINGS AND DISTANCES SHOWN ARE RECORD PER I/MAPS/18 P.C.R.  
 NO MATERIAL DISCREPANCIES WITH RECORD INFORMATION WERE FOUND.



BOOK 10 CORNER RECORDS PAGE 62