


CORNER RECORD

COUNTY OF PLACER, CALIFORNIA

City of _____ Document Number _____

Brief Legal Description LOT 158, DOLLAR POINT UNIT NO. 2, "G" MAPS 7



CORNER TYPE

COORDINATES (Optional)

Government Corner Control N. _____
 Meander Property E. _____
 Rancho Other Zone _____ Datum _____
 Date of Survey _____ Elev. _____

Corner— Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner:

~ SET 5/8" REBAR WITH ALUM. CAP LS 5886

A description of the physical condition of the monument as found and as set or reset:

~ FOUND MONUMENT AS NOTED

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land

Surveyor's Act on June 2000

Signed [Signature] L.S. or R.C.E. Number 5886



COUNTY SURVEYOR'S STATEMENT

This Corner Record was Received AUG. 28 2000 and Examined

and filed MAY 23 2001

Signed [Signature] Title Co. Surveyor

County Surveyor's Comment _____




BOOK 7 CORNER RECORDS PAGE 3

R & M ~ RECORD AND MEASURED

SCALE 1" = 40'

() ~ RECORD AS PER "G" MAPS 7



Tahoma Avenue
50' r.o.w.

fd. 3/4" pipe
LS 5549

- ~ FD. MONUMENT AS INDICATED
- ⊗ SET 5/8" REBAR LS 5886

