


CORNER RECORD

Document Number _____

City of _____

County of PLACER, California

Brief Legal Description LOT 21 SOUTHSIDE HIGHLANDS SUBD. NO. 2
BOOK "G" OF MAPS PAGE 50 P.C.R.



SEC. 13
T. 17N.
R. 15E.
M.D.M.

CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 6-29-00

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

- = FOUND 1/2" REBAR, PER "G"/MAPS/50
- = FOUND 5/8" REBAR w/PLAS. CAP L.S. 3422
- = FOUND 1/2" REBAR w/BRASS COLLAR, STAMPED L.S. 2515, PER "G"/MAPS/50

A description of the physical condition of the monument as found and as set or reset:

○ = SET 3/4" IRON PIPE w/PLASTIC PLUG L.S. 5549

JN. 00166

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on JUNE 29 2000

Signed Charles R. Sage P.L.S or R.C.E. No. L.S. 5549
LIC. EXPIRES 6-30-01




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received AUGUST 14, 2000
and examined and filed MARCH 12, 2002

Signed John H. Rietsjens P.L.S or R.C.E. No. 4323
Title COUNTY SURVEYOR


County Surveyor's Comment _____



BOOK 7 CORNER RECORDS PAGE 24

SCALE 1" = 50'

NOTE: THE BEARINGS AND DISTANCES SHOWN ARE RECORD PER G/MAPS/50. NO MATERIAL DISCREPANCIES WITH RECORD INFORMATION WERE FOUND.



BOOK 7 CORNER RECORDS PAGE 24