


CORNER RECORD

Document Number _____

City of _____

County of Placer, California

Brief Legal Description Lot 56, Chamberland Add. No. 2 BK, H. MAPS, PG. 6
O. R. P. C.



Sec. 12
T. 14N
R. 16E
M.D. 34M, Date of Survey 7/23/2001

CORNER TYPE

Government Corner	<input type="checkbox"/>	Control	<input type="checkbox"/>
Meander	<input type="checkbox"/>	Property	<input checked="" type="checkbox"/>
Rancho	<input type="checkbox"/>	Other	<input type="checkbox"/>

COORDINATES (Optional)

N. _____
E. _____
Zone NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

See sketch on Back


A description of the physical condition of the monument as found and as set or reset:

See sketch on Back

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on 8/14/2001

Signed [Signature] P.L.S or R.C.E. No. 7429



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received September 7, 2001

and examined and filed March 12, 2002

Signed [Signature] P.L.S or R.C.E. No. 4323

Title COUNTY SURVEYOR

County Surveyor's Comment _____



BOOK 7 CORNER RECORDS PAGE 27

PLAT OF SURVEY
 LOT 56, CHAMBERLANDS ADDITION UNIT No. 2
 BOOK H, OF MAPS, PAGE 6, OFFICIAL RECORDS
 PLACER COUNTY CALIFORNIA, SECTION 12,
 TOWNSHIP 14, N., RANGE 16, E., M.D.B.&M.
 SCALE 1" = 40' DATE OF SURVEY 7/23/2001

