


CORNER RECORD

COUNTY OF PLACER, CALIFORNIA

City of _____ Document Number _____

Brief Legal Description S.E. & S.W. COR'S LOT 2 BLK. "A" ICE LAKES SUB. NO. 1
BOOK "D" OF MAPS PAGE 85 P.C.R.



S.E.C. 34
T. 17N.
R. 14E.
M.D.M.

CORNER TYPE

- Government Corner
- Meander
- Rancho
- Date of Survey _____
- Control
- Property
- Other

COORDINATES
(Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner:

● = FOUND 1/2" REBAR, NO TAG

A description of the physical condition of the monument as found and as set or reset:

○ = SET 3/4" IRON PIPE W/PLASTIC PLUG L.S. 5549

JH. 01107

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land

Surveyors' Act on JUNE 28 2001.

Signed Charles R. Sage Jr. L.S. or R.C.E. Number L.S. 5549
LIC. EXP. 6-30-05




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received AUGUST 3RD 2001 and examined

and filed MARCH 20TH 2002.

Signed John H. Rietsjens Title County Surveyor



County Surveyor's Comment _____

BOOK 7 CORNER RECORDS PAGE 45

