


CORNER RECORD

Document Number _____

City of UNINCORPORATED AREA County of PLACE, California

Brief Legal Description LOT 12 SERENIE LAKES UNIT 5 & 6
BOOK J MAPS PAGE 57 P.C.R. + CERT. OF CORR. 1487/O.R./29



SEC. 27
T. 17N.
R. 14E.
M.O.M.

CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 6/20/06

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

- = FOUND 5/8" REBAR W/PLASTIC CAP L.S. 3332, PER J/MAPS/67
- = FOUND 3/4" IRON PIPE W/PLASTIC PLUG, L.S. 5549, PER Z/CR/136

* NOTE: LOT 12 SHOWN AS LOT 14 ON SHEET 6 PER J/MAPS/67
CORRECTED PER CERT. OF CORRECTION BK. 1487 O.R. PG. 29

A description of the physical condition of the monument as found and as set or reset:

- = SET BATHY MONUMENT W/NAI + TAG L.S. 5549

JN. 06022

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on JUNE 23 2006

Signed [Signature] P.L.S or R.C.E. No. L.S. 5549
LIC. EXP. 6/30/07

COUNTY SURVEYOR'S STATEMENT



This Corner Record was received _____

and examined and filed JANUARY 29, 2008

Signed Charles B. Grant P.L.S or R.C.E. No. 6158

Title DEPUTY COUNTY SURVEYOR


County Surveyor's Comment _____



BOOK 11 CORNER RECORDS PAGE 63

NOTE: THE BEARING AND DISTANCES SHOWN ARE RECORD PER J/MAPS/67 P.C.R.
 NO MATERIAL DISCREPANCIES WITH RECORD INFORMATION WERE FOUND.

SCALE: 1"=60'



BOOK 11 CORNER RECORDS PAGE 63

ICE LAKES UNIT NO. 2
 BLOCK I
 G/MAPS/1 P.C.R.