

CORNER RECORD


Document Number 20070026

City of Granite Bay

County of Placer

California

Brief Legal Description Lot 21 Walden Woods Unit No. 1 (K-45)



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 11/05/07

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

TUN R7E MDM

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found CL and lot corners as per K-45 in good condition and as described.

A description of the physical condition of the monument as found and as set or reset: _____
Set 5/8" iron rod capped PLS 4327 flush with the ground at record bearings
and distances from the found CL monuments.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Land Surveyor's Act on November 6 2007


Signed Gary K. Sheldon P.L.S. or R.C.E. No. 4327



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____
 and examined and filed MARCH 3 2008

Signed Charles B. Grant P.L.S. or R.C.E. No. 6158
 Title DEPUTY COUNTY SURVEYOR LICENSE EXPIRES 3-31-08



County Surveyor's Comment _____

BOOK 11 CORNER RECORDS, PAGE 82

