


# CORNER RECORD

Document Number \_\_\_\_\_

City of \_\_\_\_\_ County of Placer, California

Brief Legal Description T.14N., R.13E., M.D.B.M 1/4 corner between sections 20 and 21



### CORNER TYPE

Government Corner  Control   
 Meander  Property   
 Rancho  Other

Date of Survey October 12, 2006

### COORDINATES(Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ NAD27  NAD83   
 NAD83 Epoch \_\_\_\_\_  
 Elev. \_\_\_\_\_  
 Vert. Datum: NGVD29  NADV88   
 Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
Found 2 1/2" GLO cap on 1" Iron Pipe monument, disturbed by suppression activities during 2001 wildfire. Found two bearing trees: a well charred pine stump with nails and melted remnants of government survey signs to NW, a charred pine snag with healed blaze and melted remnants of government signs to the SE.

A description of the physical condition of the monument as found and as set or reset: Reset monument in a 36" diameter mound of stone, at record distances from bearing trees per Record of Survey Bk 9 Pg 29. Added "2006" stamping to cap. Set a 3/4" Iron Rod at N58°W 7.2ft (compass).

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on October 19 2006

Signed Mary A. Niederberger-Lee P.L.S. or R.C.E. No.: 5716




### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received OCT 24 and examined and filed NOVEMBER 14, 2007

Signed Charles B. Grant P.L.S. or R.C.E. No.: LS 6158

Title DEPUTY COUNTY SURVEYOR


County Surveyor's Comment \_\_\_\_\_





BOOK 11 CORNER RECORDS PAGE 9

T14N R13E

Charred Stump



No Scale



Charred Pine Snag w/ Healed Blaze

- ( ) - Record of Survey Book 9 Page 29
- { } - GLO 1926