


# CORNER RECORD

Document Number \_\_\_\_\_

City of N/A County of PLACER, California

Brief Legal Description PORTION N.E. 1/4 SECTION 22, T.16N., R.17E. M.D.B. & M.



### CORNER TYPE

### COORDINATES (Optional)

- Government Corner  Control   
 Meander  Property   
 Rancho  Other

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_

Date of Survey November 4, 2005

Elev. \_\_\_\_\_

T.16N., R.17E., MDM

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

● ■ FOUND MONUMENT AS SHOWN HEREON

USED NEAREST FOUND MONUMENTS WITHIN UNIT TO REESTABLISH PROPERTY  
 CORNERS AS SHOWN HEREON.

A description of the physical condition of the monument as found and as set or reset:

○ SET MONUMENT AS SHOWN

FOUND MONUMENTS IN GOOD CONDITION.


CLEARED BRUSH AND PLACED LATH AT FOUND AND SET MONUMENTS.

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyors' Act on OCTOBER 3 2007

Signed [Signature] L.S. or R.C.E. Number R.C.E. 20257




### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received OCT. 5 2007 and examined

and filed NOVEMBER 14 2007

Signed Charles B. Grant Title DEPUTY COUNTY SURVEYOR  
LS 6158




County Surveyor's Comment :

BOOK 11 CORNER RECORDS PAGE 12

**NOTES:**

- ■ ~ FOUND MONUMENT AS NOTED
- ~ SET MONUMENT AS NOTED RCE 20257



BOOK 11 CORNER RECORDS PAGE 12

**BASIS OF BEARINGS:**

THE BASIS OF BEARINGS IS IDENTICAL TO THAT SHOWN ON RECORD OF SURVEY No. 2752, DATED DECEMBER 2005. AS SHOWN IN BOOK 19 SURVEYS AT PAGE 32 PLACER COUNTY OFFICIAL RECORDS.

