


CORNER RECORD

Document Number _____

City of _____

County of PLACER, California

Brief Legal Description LOT 50, TAHOE WOODS UNIT No. 1 SUB. I/MAPS/30, O.R.P.C.



CORNER TYPE

SEC. 13 Government Corner Control

T. 15N. Meander Property

R. 16E. Rancho Other

M.D.B. $\frac{1}{2}$ M. Date of Survey 5-10-2007

COORDINATES (Optional)

N. _____

E. _____

Zone _____ NAD27 NAD83

NAD83 Epoch _____

Elev. _____

Vert. Datum: NGVD29 NAVD88

Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

USED THE RECORD DIMENSIONS AND THE FOUND MONUMENTS PER I/MAPS/30, O.R.P.C., TO REESTABLISH THE MISSING WESTERLY CORNER AS SHOWN ON THE ACCOMPANYING PLAT.

A description of the physical condition of the monument as found and as set or reset:


SET 5/8" REBAR WITH YELLOW PLASTIC CAP MARKED LS 7429.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on May 17 2007

Signed [Signature] P.L.S or R.C.E. No. 7429



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____

and examined and filed Nov. 29 2007

Signed Charles B. Grant P.L.S or R.C.E. No. LS 6158

Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____





BOOK 11 CORNER RECORDS PAGE 17

PLAT OF SURVEY

LOT 50, TAHOE WOODS UNIT NO. 1 SUBDIVISION, BOOK 1 OF MAPS AT PAGE 30, OFFICIAL RECORDS PLACER COUNTY, CALIFORNIA. A PORTION OF SECTION 13, TOWNSHIP 15 N., RANGE 16 E., M.D.B. & M.

SCALE 1" = 40' DATE OF SURVEY 5/10/2007



NOTE:

ALL BEARINGS AND DISTANCES SHOWN HEREON ARE RECORD PER I/MAPS/30, O.R.P.C.

- FOUND MONUMENT AS SHOWN HEREON
- SET 5/8" REBAR WITH YELLOW PLASTIC CAP L.S. 7429
- DIMENSION PT (NOTHING FOUND OR SET)

J/N 1431.00

BOOK 11 CORNER RECORDS PAGE 17