


CORNER RECORD

Document Number _____

City of ROCKLIN

County of PLACER, California

Brief Legal Description: PARCEL 1, P.M. 31-120
PORTION OF THE S.E. 1/4 OF SECTION 20, T.11N., R.7E., M.D.M.



CORNER TYPE

COORDINATES
(Optional)

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey MARCH 8, 2006

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: _____

REESTABLISHED THE MONUMENTS OF PARCEL 1,
P.M. 31-120, USING FOUND MONUMENTS SHOWN PAGE 2.

A description of the physical condition of the monument as found and as set or reset:

1. FOUND MONUMENTS AS SHOWN ON PAGE 2.
2. SET MONUMENTS AS SHOWN ON PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the land Surveyors' act on JAN. 04 2007


Signed *Gene E. Thorne* or R.C.E. Number 20462
 Reg. Exp. Date 09-30-07



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ 20____ and examined and filed DEC 24 2007.


Signed *Charles B. Grant* Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____

BOOK 11 CORNER RECORDS PAGE 26

LOT 226 SUBDIVISION I-77



BOOK 11 CORNER RECORDS PAGE 26

LEGEND:

- FOUND 3/4" REBAR WITH TAG-L.S. 4082 UNLESS OTHERWISE NOTED
- ⊗ SET 3/4" CAPPED IRON PIPE STAMPED "RCE 20462-2006" UNLESS OTHERWISE NOTED

REFERENCES:

P.M. 31-120

BASIS OF BEARING:

IDENTICAL TO THAT OF P.M. 31-120