


CORNER RECORD

Document Number _____

City of _____

County of PLACER, California

Brief Legal Description A POR. OF LOTS 3 & 4, SUNNYSIDE TRACT, A/MAPS/14, O.R.P.C.



SEC. 24
T. 15 N.
R. 16 E.
M.D.B. & M.

CORNER TYPE
 Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 12-7-2006

COORDINATES (Optional)
 N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

USED THE DIMENSIONS AND FOUND MONUMENTS AS SHOWN ON 12/ROS/148, O.R.P.C., TO REESTABLISH THE MISSING CORNER AS SHOWN ON THE ACCOMPANYING PLAT.


A description of the physical condition of the monument as found and as set or reset:

SET 5/8" REBAR WITH YELLOW PLASTIC CAP MARKED LS 7429.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on December 13, 2006

Signed [Signature] P.L.S. or R.C.E. No. 7429



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received _____

and examined and filed JANUARY 15, 2008

Signed Charles B. Grant P.L.S. or R.C.E. No. 6158

Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____




BOOK 11 CORNER RECORDS PAGE 46


PLAT OF SURVEY

A POR. OF LOTS 3 & 4, SUNNYSIDE TRACT, BOOK A OF MAPS, AT PAGE 14, OFFICIAL RECORDS PLACER COUNTY, CALIFORNIA. A PORTION OF THE S.E. 1/4 OF SECTION 24, TOWNSHIP 15 N., RANGE 16 E., M.D.B. & M.

SCALE 1" = 40' DATE OF SURVEY 12/7/2006



BOOK 11 CORNER RECORDS PAGE 46



- FOUND MONUMENT AS SHOWN HEREON
- SET 5/8" REBAR WITH YELLOW PLASTIC CAP L.S. 7429
- (1) RECORD PER 12/ROS/148, O.R.P.C.

J/N 1407.00