


CORNER RECORD

Document Number _____

City of _____

County of PLACER, California

Brief Legal Description LOT 32 PAINTED ROCK ESTATES
BOOK "V" OF MAPS PAGE 2 P.C.R.



SEC. 28
T. 16 N.
R. 16 E.
M. D. M.

CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 8-14-02

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

● = FOUND 3/4" REBAR W/ PLAS. CAP, L.S. 4976
▼ = FOUND COPPER WELD IN MONUMENT BOX, L.S. 4751

A description of the physical condition of the monument as found and as set or reset:

○ = SET 3/4" IRON PIPE W/ PLASTIC PLUG, L.S. 5549
⊗ = SET CHISEL CROSS ON ROCK 1' BELOW GROUND.

J.N. 02133

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on AUGUST 15 2002

Signed Charles R. Sage Jr. P.L.S or R.C.E. No. L.S. 5549
LIC. EXP. 6-30-02



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received AUGUST 20, 2002

and examined and filed JULY 30 2003

Signed Charles B. Grant P.L.S or R.C.E. No. LS 6158

Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____



BOOK 8 CORNER RECORDS PAGE 8

LOT 31

CAR MISSING

N 01° 59' 53" W
33.76'

N 70° 30' 17" W
73.03'

N 70° 26' 05" W
42.00'

R = 42'
A = 65° 53' 07"
L = 48.30'

SHOSHONE WAY

LOT 32

N 02° 03' 51" E
199.98'

N 43° 32' 07" E
174.28'

LOT 33

SCALE 1" = 40'

NOTE: THE BEARINGS AND DISTANCES SHOWN ARE RECORD PER "V" MAPS/2. NO MATERIAL DISCREPANCIES WITH RECORD INFORMATION WERE FOUND.