


CORNER RECORD

COUNTY OF PLACER, CALIFORNIA

City of _____ Document Number _____

Brief Legal Description LOT 14, GRANITE BAY VISTA UNIT No. 2, F MAPS 37 PCR



*T.10N.
R.8E.*

CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 08-08-02

COORDINATES (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner:

FOUND 1/2" REBAR ACCEPTED AS REAR LOT CORNERS
ATTACHED TAG STAMPED L.S. 5123. AS SHOWN

A description of the physical condition of the monument as found and as set or reset:

FROM FOUND MONUMENTS AND RECORD DATA PER F MAPS 37
P.C.R., SET 1/2" REBAR TAGGED L.S. 5123 AT FRONT
CORNERS OF LOT AS SHOWN

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land

Surveyors' Act on AUGUST 2002.

Signed Steven A. Gardner (L.S.) or R.C.E. Number L.S. 5123
EXPIRATION DATE: 06/30/03




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received August 30 2002 and examined

and filed JUNE 24 2003.

Signed Charles B. Grant L.S. 6158 Title DEPUTY COUNTY
SURVEYOR



County Surveyor's Comment _____

BOOK 8 CORNER RECORDS PAGE 10

