


CORNER RECORD

COUNTY OF PLACER, CALIFORNIA

City of ROSEVILLE

Document Number _____

Brief Legal Description LOT 74 CREEKSIDE ESTATES UNIT No. 2 O MAPS 40



T. 10N.
R. 6E.

CORNER TYPE

- Government Corner
- Meander
- Rancho
- Date of Survey 08-06-03
- Control
- Property
- Other

COORDINATES
(Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner:

- ⊙ Found Copperweld L.S. 3923 in Mon. Box
- Found 3/4" Rebar flush with A.C.
- Found Gash at back of sidewalk
- ⊕ Set 3/4" Rebar plastic Cap stamped L.S. 5123
- Used found monuments and record data per O.B.M. 40 to reestablish location of set monuments.

A description of the physical condition of the monument as found and as set or reset:

○ Dimension point nothing found or set

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land

Surveyors' Act on 08-06- 2003.

Signed Steven A. Gardner (L.S.) or R.C.E. Number 5123
 EXPIRATION DATE: 06-30-07


COUNTY SURVEYOR'S STATEMENT

This Corner Record was received OCT 2 2003 and examined

and filed OCT 2 2003.

Signed Charles B. Grant Title DEPUTY COUNTY SURVEYOR
LS 6158

County Surveyor's Comment _____



BOOK 8 CORNER RECORDS PAGE 49

