


CORNER RECORD

Document Number 20080071

City of \_\_\_\_\_

County of PLACER, California

Brief Legal Description LOTS 107 & 108, LOS LAGOS U#2, Q MAPS 37, S-25, T11N, R7E, MDM



T11N,  
R7E,  
MDM

CORNER TYPE

- Government Corner  Control
- Meander  Property
- Rancho  Other
- Date of Survey \_\_\_\_\_

COORDINATES (Optional)

- N. \_\_\_\_\_
- E. \_\_\_\_\_
- Zone \_\_\_\_\_ NAD27  NAD83
- NAD83 Epoch \_\_\_\_\_
- Elev. \_\_\_\_\_
- Vert. Datum: NGVD29  NAVD88
- Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
HELD EXISTING CENTERLINE CONTROL MONUMENTS AND CHECKED INTO FOUND ORIGINAL LOT CORNERS

A description of the physical condition of the monument as found and as set or reset: MONUMENTS FOUND IN EXCELLENT CONDITION (SEE MAP OTHER SIDE) SET 3/4" REBAR 2' LONG, WITH 2" ALUM. CAP STAMPED LS 6013


SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on OCTOBER 20TH 2008  
Signed [Signature] P.L.S or R.C.E. No. 6013




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received \_\_\_\_\_  
and examined and filed DEC. 3, 2008  
Signed [Signature] P.L.S or R.C.E. No. 6158  
Title COUNTY SURVEYOR



County Surveyor's Comment \_\_\_\_\_


BOOK 12 OF CORNER RECORDS, PAGE 39



SCALE 1" = 100'

- ⊕ FD. 2" BRASS CAP STAMPED LS 4715 IN MONUMENT BOX
- FD. 3/4" I.P. PLUGGED LS 4715
- SET 3/4" ROD WITH 2" ALUM. CAP STAMPED LS 6013

CURVE TABLE				
CURVE	LENGTH	RADIUS	CHORD BRG	CHD
C1	52.36	50.00	N83°54'51"E	50.00
C2	68.62	50.00	N14°35'34"E	63.36
C3	15.54	37.50	S12°51'13"E	15.43



ALL COURSES MEASURED AND RECORD  
PER Q / MAPS / 37 , PCR .