


CORNER RECORD

COUNTY OF PLACER, CALIFORNIA

City of _____ Document Number 20100002

Brief Legal Description Lot 6, Block N, Squaw Valley Estates No.3 Subdivision, E/Maps/93



CORNER TYPE

T16N Government Corner Control
 Meander Property
 R16E Rancho Other
 Date of Survey 08-04-09

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: See sketch on back.

Found 5/8" rebars in record position at the Southwest corner of Lot 5, Block N and Southeast corner of Lot 7, Block N. Found 5/8" rebars in record position at Northwest and Northeast corners of Lot 8, Block L and Northwest corner of Lot 7, Block M.

A description of the physical condition of the monument as found and as set or reset: See sketch on back.

Set 5/8" rebar tagged LS 6819 in record location.


SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on December 21, 2009. Signed [Signature] P.L.S. or R.C.E. No. 6819



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received and examined and filed, August 4, 2010. Signed [Signature] (P.L.S.) or R.C.E. No. 6584. Title, Deputy County Surveyor. County Surveyor's Comment _____



BOOK 13 CORNER RECORDS PAGE 91

