

CORNER RECORD

Document Number 20080074


City of _____

County of PLACER, California

Brief Legal Description LOT 65 & 66 AND CENTERLINE OF OLANA DRIVE, MARTIS CAMP UNIT No.1 PER BOOK BB, PG. 17, AS SHOWN ON SHEET 47 OF 56.

CORNER TYPE

COORDINATES(Optional)



S26
T17N
R16E

Government Corner Control
 Meander Property
 Rancho Other

Date of Survey NOV. 3, 2008

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert.Datu: NGVD29 NADV88
 Meas.Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
REESTABLISHED PROPERTY CORNER AND CENTERLINE PER RECORD INFORMATION AND FOUND MONUMENTS AS SHOWN ON REVERSE.

A description of the physical condition of the monument as found and as set or reset: SET A 5/8" REBAR AND PLASTIC CAP STAMPED "LS 6459" AT PROPERTY CORNERS AND CHISEL MARKS FOR INTERSECTION ON A STORM DRAIN MANHOLE RIM, FOUND ALL OTHER MONUMENTS AS SHOWN ON REVERSE IN GOOD CONDITION.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on NOV. 3, 2008.

Signed Stanley W. Ziebarth P.L.S. or ~~R.C.E.~~ No. 6459



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received _____ and examined _____

and filed APRIL 14, 2009.

Signed Charles B. Grant (P.L.S.) or R.C.E. No.: 6158
 LICENSE EXPIRES 3-31-10

Title COUNTY SURVEYOR

County Surveyor's Comment _____



BOOK 13 CORNER RECORDS, PAGE 12



1"=100'

LOT
T-1

NOTE:
ALL BEARINGS AND DISTANCES SHOWN
HEREON ARE RECORD PER BB MAPS 17,
OPCR, SEE SHEET 47 OF 56.

67

L=120.75'
R=320.00'
Δ=21°37'15"

80

L=314.76'
R=300.00'
Δ=60°06'54"
(R&M)

L=214.99'
R=320.00'
Δ=38°29'39"

66

81


N53°42'00"W
286.88' (R&M)

65

L=738.53'
R=295.00'
Δ=143°26'24"
(R&M)

64

82



QANA DRIVE

83

LEGEND

- ~ FOUND 1" IP & Plastic Cap "LS 4715" in well per Book BB of Maps, Page 17
- ~ FOUND Rebar & Plastic Cap "LS 4715" per Book BB of Maps, Page 17
- ▲ ~ FOUND 3/4" IP & Plastic Cap "LS 4715" per Book BB of Maps, Page 17
- △ ~ SET Chisel Marks for Intersection on Storm Drain Manhole Rim (See Detail)
- ~ SET 5/8" Rebar and Plastic Cap "LS 6459"