


CORNER RECORD

COUNTY OF PLACER, CALIFORNIA

City of LOOMIS, COUNTY OF PLACER, CALIFORNIA Document Number 20090054

Brief Legal Description TRACT NO. 758 CLOS DU LAC, THE NW¼ OF SECTION 17, T 11 N, R8E. MDM (SMAPS 65)



S. 17

CORNER TYPE

COORDINATES

(Optional)

T. 11 N.

Government Corner

Control

N. _____

Meander

Property

E. _____

R. 8 E.

Rancho

Other

Zone _____ Datum _____

Date of Survey OCTOBER 14, 2008

Elev. _____

Corner--- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner: ORIGINAL RAILROAD SPIKES WERE FOUND AT CENTERLINE MONUMENT LOCATIONS. MONUMENTS WERE DOUBLE-TIED TO RE-ESTABLISH POSITIONS. AFTER MONUMENTS WERE DESTROYED BY ROAD RECONSTRUCTION, RAILROAD SPIKES WITH PUNCH STAMPED LS 4922 WERE SET AT FOUND POSITIONS. NEW MONUMENTS WERE SET USING THE SAME DOUBLE-TIE PROCEDURE.

A description of the physical condition of the monument as found and as set or reset: _____

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on AUGUST 3 2009.

Signed [Signature]

L.S. or R.C.E. Number 4922 Expiration Date 12/31/10




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ 20____

and examined and filed SEPT. 8 2009.

Signed Charles B. Grant Title COUNTY SURVEYOR

L.S. or R.C.E. Number 6158 Expiration Date 3-31-10



County Surveyor's Comment _____

BOOK 13 CORNER RECORDS PAGE 41

- FOUND MON A - 3/4" REBAR NO TAG
- FOUND MON B - 2" IRON PIPE W/ CAP
- RESET CENTERLINE MONUMENT WITH RAILROAD SPIKE AND PUNCH AFTER ROAD RECONSTRUCTION STAMPED LS 4922

STAMPED 1/4 SEC. 17 T7N., R8E, 2004

