


CORNER RECORD

COUNTY OF PLACER, CALIFORNIA

City of _____ Document Number 20100062

Brief Legal Description K-MAPS - 66 SIERRA OAKS TRACT No. 337



S. 33

CORNER TYPE

COORDINATES

T. 11 N.

Government Corner

Control

N. _____

R. 7 E.

Meander

Property

E. _____

Rancho

Other

Zone _____ Datum _____

Date of Survey _____

Elev. _____

Corner--- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner:
FOUND 1/2" PIPE TAGGED LS4715 IN TRAVELED WAY OF BARTON Rd Per
MAP of SIERRA OAKS, TRACT No. 337, Book K of MAPS, PAGE 66 O.R.P.C.
FROM FOUND MONUMENT ESTABLISHED REFERENCE POINTS PRIOR TO
ASPHALT OVERLAY.

A description of the physical condition of the monument as found and as set or reset:
FROM REFERENCE POINTS SET MAG-NAIL W/ 1/4" BRASS TAG STAMPED
" PLACER CO SURVEYOR" CENTERED OVER FOUND MONUMENT

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act

on December 6 2010

Signed [Signature]

L.S. or R.C.E. Number 7887 Expiration Date MAR. 31, 2011




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ 20____

and examined and filed DECEMBER 28 2010

Signed Leslie Ambery Title Deputy


L.S. or R.C.E. Number 6584 Expiration Date 12-31-11



County Surveyor's Comment _____

BOOK 14 CORNER RECORDS PAGE 25

Fd. 1-1/2" PIPE, TAGGED LS 4715,
SET 1-1/4" BRASS TAG STAMPED
"PLACER CO SURVEYOR"



K-MAPS-66

NOTE:
THIS CORNER RECORD REPRESENTS THE
AS FOUND LOCATION OF THE MONUMENTS
SHOWN HEREON. NO SURVEY HAS BEEN
MADE OF SAID MONUMENTS.