


CORNER RECORD

COUNTY OF PLACER, CALIFORNIA

City of _____ Document Number 20110028

Brief Legal Description WEST LINE PARCEL "B" 11 PM 19



SEC. 23,
T. 12 N.,
R. 7 E.

CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey JUNE 20 2011

COORDINATES
(Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner:

RESET OR REPLACED CORNERS FROM FOUND
MONUMENTS OF RECORD FROM 11/PM/19

A description of the physical condition of the monument as found and as set or reset:

SET 3/4" IRON PIN W/ PLASTIC CAP STAMPED L.S. 3735
AT RECORD POSITION at positions indicated by σ
symbol

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land

Surveyors' Action JUNE 20 20 11

Signed Gerald F. Ding L.S. or R.C.E. Number LS 3735




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ 20 _____ and examined


and filed JULY 7, 20 11

Signed Leslie Ambsberry PLS 6584 Title Deputy



County Surveyor's Comment _____

BOOK 14 CORNER RECORDS PAGE 64



: Fd. 3/4" iron pipe displaced, replaced w/ 3/4" pin w/ cap LS 3735

Fence 3' west

Parcel "A"
11 PM 19

N7°16'09"W
279.00'

Parcel "B"
11 PM 19

Fence 3' East

: Set 3/4" iron pin w/ cap LS 3735

N4°00'00"W
105.00'

Fence 3' West

: Fd. 3/4" Iron Pipe, LS 4338
(25' R.P.)

N4°00'00"W
25.00'

23

: Fd. Iron Hub over Granite Mon.

N89°08'43"E

508.58'

SEC. COR.

22

27

26

BOOK 14 CORNER RECORDS PAGE 64