


CORNER RECORD

Document Number 20110032

City of _____ County of PLACER, California

Brief Legal Description LOT 151, ALPINE PEAKS UNIT NO.1, SUBDIVISION 1-MAPS-61, O.R.P.C.



Sec. 16
T. 15 S
R. 16 E.
M.D.B. & M.

CORNER TYPE
Government Corner Control
Meander Property
Rancho Other
Date of Survey 7/6/2011

COORDINATES (Optional)
N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial


Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
USED RECORD DIMENSIONS AND FOUND MONUMENTS PER 1-MAPS-61
O.R.P.C. TO REESTABLISH THE MISSING CORNER OF LOT 151
AS SHOWN ON ACCOMPANYING PLAT.

A description of the physical condition of the monument as found and as set or reset:
SET 5/8" REBAR WITH YELLOW PLASTIC CAP LS-7429
FOUND MONUMENT AS SHOWN ON PLAT


SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on July 06, 2011
Signed [Signature] P.L.S or R.C.E. No. 7429



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____
and examined and filed July 25, 2011
Signed [Signature] P.L.S or R.C.E. No. 6584
Title Deputy County Surveyor



County Surveyor's Comment _____



BOOK 14
CORNER RECORDS
PAGE 68

BOOK 14 CORNER RECORDS PAGE 68

PLAT OF SURVEY

LOT 151, ALPINE PEAKS UNIT NO. 1 SUBDIVISION, AS FILED IN BOOK 1 OF MAPS AT PAGE 61, OFFICIAL RECORDS PLACER COUNTY, CALIFORNIA. A PORTION OF SECTION 16, TOWNSHIP 15 N., RANGE 16 E., M.D.B. & M.

SCALE 1" = 40' DATE OF SURVEY 7/6/2011



- FOUND MONUMENT AS SHOWN HEREON
- NOTE: 5/8" REBAR APPEAR TO HAVE BEEN SET, INSTEAD OF 1/2" REBAR OF WHICH NONE WERE FOUND, PER I-MAPS-61, O.R.P.C.
- SET 5/8" REBAR WITH YELLOW PLASTIC CAP L.S. 7429

J/N 1943.00