


CORNER RECORD

COUNTY OF PLACER, CALIFORNIA

City of Loomis

Document Number 20110055

Brief Legal Description Parcel A of PM No. 70119 - Book 2 PM Page 70



S. 14
T. 11 N
R. 7 E

CORNER TYPE

- Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 11/29/11

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner --- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner:
Three property corners shown for Parcel A were recovered in good condition. The southeast corner (on the right-of-way line of Val Verde Road) was searched for and not found. A new monument was set in its' place at record position.

A description of the physical condition of the monument as found and as set or reset: _____
Three corners were found as stated on the parcel map. The southeast corner was reset with a 3/4" inside diameter x 24" long iron pipe with a plastic plug: LS 6376.

Re-set corner is shown on sketch.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction
 in conformance with the Professional Land Surveyors' Act
 on March 8 20 12
 Signed Richard A Marino
 L.S. or R.C.E. Number 6376 Expiration Date _____



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ 20_____
 and examined and filed MARCH 28, 2013 20_____
 Signed Leslie Amstutz Title Deputy County Surveyor
 L.S. or R.C.E. Number 6584 Expiration Date 12-31-2013




County Surveyor's Comment _____

BOOK 15 CORNER RECORDS PAGE 8

LEGEND:

- ⊘ SET 3/4" REBAR W/ PLASTIC PLUG; L.S.6376
- FD. 3/4" REBAR W/COPPER SLEEVE L.S.2515 PER 2 PM 70
- DIMENSION POINT
- (1) RECORD PER 2 PM 70



TATE
DOC NO. 2008-0042140

BOOK 15 CORNER RECORDS PAGE 8

