


CORNER RECORD

Document Number 20110025

City of _____

County of PLACER, California

Brief Legal Description LOTS 50 & 52, TANGUE SIERRA ESTATES SUBDIVISION, F/MAPS/4 O.R.P.C.



Sec 7
 T.15 N.
 R.17. E.
 M.D.B&M.

CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 6/16/2011

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial


Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
USED RECORD DIMENSIONS AND FOUND MONUMENTS PER
F/MAPS/4 O.R.P.C. TO REESTABLISH THE MISSING CORNERS
OF LOTS 50 AND 52, AS SHOWN ON PLAT.

A description of the physical condition of the monument as found and as set or reset:
Q SET 5/8" REBAR WITH YELLOW PLASTIC CAP LS-7429
• FOUND MONUMENT AS SHOWN ON PLAT

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on June 17, 2011
 Signed [Signature] P.L.S. or R.C.E. No. 7429



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ and examined and filed May 14, 2012
 Signed [Signature] P.L.S. or R.C.E. No. 6584
 Title Deputy County Surveyor



County Surveyor's Comment _____

BOOK 15 CORNER RECORDS PAGE 26

