


# CORNER RECORD

Document Number 20120054

City of \_\_\_\_\_

County of Placer, California

Brief Legal Description Lot 116, Kingswood Estates #1 (I-11, 1966)



T16N R17E MDM

### CORNER TYPE

- Government Corner  Control
- Meander  Property
- Rancho  Other

Date of Survey July 19, 2012

### COORDINATES(Optional)

- N. \_\_\_\_\_
- E. \_\_\_\_\_
- Zone \_\_\_\_\_ NAD27  NAD83
- NAD83 Epoch \_\_\_\_\_
- Elev. \_\_\_\_\_
- Vert. Datum: NGVD29  NADV88
- Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
Found monuments per Bk I MAPS 11, used to re-establish the NE'ly corner of lot 32

A description of the physical condition of the monument as found and as set or reset: \_\_\_\_\_  
set 5/8" rebar with topper (LS 5716)

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on August 7, 2012.

Signed Mary A. Niederberger-Lee P.L.S. or R.G.E. No.: 5716




### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received \_\_\_\_\_ and examined \_\_\_\_\_ and filed October 30, 2012.

Signed Leslie Amsterry P.L.S. or R.G.E. No.: 6584


Title Deputy County Surveyor

County Surveyor's Comment \_\_\_\_\_



BOOK IS CORNER RECORDS PG 57

BH 15 CORNER RECORDS PG 57



LOCATION Kingswood Estates #1 (I-11) 7878 Lincoln Green	
FILENAME 111-130-014 -022 CC.TRV	SURVEY DATE 7/19/2012



- ⊙ Set 5/8" rebar/topper (LS 5716)
- Found 1/2" rebar per sub'd map
- nothing found, nothing set
- ( ) record bearing and distance from sub'd map