


CORNER RECORD

Document Number 20120056

City of Homewood County of PLACER, California

Brief Legal Description Lot 5, Blackwood Cove/ Placer County, CA., Bk F/Maps/Pg.3



CORNER TYPE

- Government Corner Control
 Meander Property
 Rancho Other

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____

Date of Survey AUGUST 15, 2012

Elev. _____

T.15 N., R.16 E., MDM

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND MONUMENTS AS SHOWN ON PAGE 2

USED NEAREST FOUND MONUMENTS WITHIN UNIT TO REESTABLISH PROPERTY

CORNERS AS SHOWN HEREON.

FOUND MONUMENTS IN GOOD CONDITION.

A description of the physical condition of the monument as found and as set or reset: _____

SET MONUMENT AS SHOWN ON PAGE 2

PLACED LATH AT SET MONUMENT.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyors' Act on AUGUST 21 2012

Signed [Signature] L.S. or R.C.E. Number R.C.E. 20257




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ and examined

and filed November 1, 2012 20 _____

Signed [Signature] Title Deputy County Surveyor

County Surveyor's Comment : _____




BH 15 CORNER RECORDS, PG 59

NOTES:

- BEARINGS AND DISTANCES SHOWN ARE RECORD PER F/MAPS/3
- FOUND 1/2" REBAR NO TAG PER F/MAPS/3 & 2/CR/75
- FOUND 3/4" REBAR NO TAG PER F/MAPS/3 & 2/CR/75
- FOUND 5/8" REBAR W/PLASTIC CAP LS 6230
- SET 5/8" REBAR W/PLASTIC CAP RCE 20257



1"=50'



BH 15 CORNER RECORDS, PG 59