

# CORNER RECORD

Document Number 20140008  
 County of Placer, California

City of Lincoln

Brief Legal Description Parcels A-G per Book 22 of Parcel Maps, Page 13

CORNER TYPE	COORDINATES(Optional)															
<table border="0"> <tr> <td style="width:15%">SEC. 7</td> <td>Government Corner</td> <td><input type="checkbox"/></td> <td>Control</td> <td><input type="checkbox"/></td> </tr> <tr> <td>T. 12 N</td> <td>Meander</td> <td><input type="checkbox"/></td> <td>Property</td> <td><input checked="" type="checkbox"/></td> </tr> <tr> <td>R. 6 E</td> <td>Rancho</td> <td><input type="checkbox"/></td> <td>Other</td> <td><input type="checkbox"/></td> </tr> </table>	SEC. 7	Government Corner	<input type="checkbox"/>	Control	<input type="checkbox"/>	T. 12 N	Meander	<input type="checkbox"/>	Property	<input checked="" type="checkbox"/>	R. 6 E	Rancho	<input type="checkbox"/>	Other	<input type="checkbox"/>	N. _____ E. _____ Zone _____ NAD27 <input type="checkbox"/> NAD83 <input type="checkbox"/> NAD83 Epoch _____ Elevation _____ Vert. Datum: NGVD29 <input type="checkbox"/> NAV88 <input type="checkbox"/> Meas. Units: Metric <input type="checkbox"/> Imperial <input type="checkbox"/>
SEC. 7	Government Corner	<input type="checkbox"/>	Control	<input type="checkbox"/>												
T. 12 N	Meander	<input type="checkbox"/>	Property	<input checked="" type="checkbox"/>												
R. 6 E	Rancho	<input type="checkbox"/>	Other	<input type="checkbox"/>												
Date of Survey <u>11-8-13</u>																


Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
Found 1 1/2" Bronze Capped Copperwelds Stamped R.C.E. 11425 along Flight-  
line Drive. Prior to construction on Flightline Drive monuments were tied  
out and replaced once construction was completed.

A description of the physical condition of the monument as found and as set or reset: Set 3/4" iron pipe with a  
plastic cap stamped L.S. 6947 at centerline of Flightline Drive at  
property corners.

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with  
 the Professional Land Surveyor's Act on March 6, 2014  
 Signed [Signature] P.L.S. or R.C.E. Number L.S. 6947



### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received \_\_\_\_\_ and examined  
 and filed March 20, 2014  
 Signed [Signature] P.L.S. or R.C.E. Number 6584  
 Title County Surveyor  
 County Surveyor's Comment \_\_\_\_\_



BOOK 16 CORNER RECORDS, PAGE 91

FOUND 1 1/2" BRONZE CAPPED COPPERWELD  
STAMPED RCE 11425 (1)  
DESTROYED DURING CONSTRUCTION.  
SET 3/4" IRON PIPE WITH  
PLASTIC CAP STAMPED L.S. 6947.

**LEGEND**

- SET 3/4" IRON PIPE WITH PLASTIC CAP STAMPED L.S. 6947

CITY OF LINCOLN AIRPORT

PARCEL G  
22 P.M. 13

PARCEL F  
22 P.M. 13

PARCEL E  
22 P.M. 13

PARCEL D  
22 P.M. 13

PARCEL B  
22 P.M. 13

PARCEL C  
22 P.M. 13

PARCEL A  
22 P.M. 13

FLIGHTLINE DRIVE

SCALE 1" = 150'

FOUND 1 1/2" BRONZE CAPPED COPPERWELD  
STAMPED RCE 11425 (1)  
DESTROYED DURING CONSTRUCTION.  
SET 3/4" IRON PIPE WITH  
PLASTIC CAP STAMPED L.S. 6947.

FOUND 1 1/2" BRONZE CAPPED COPPERWELD  
STAMPED RCE 11425 (1)  
DESTROYED DURING CONSTRUCTION.  
SET 3/4" IRON PIPE WITH  
PLASTIC CAP STAMPED L.S. 6947.

N15°09'53"W  
429.50'

N15°09'53"W  
220.00'

N15°09'53"W  
220.00'

N15°09'53"W  
440.00'

N15°09'53"W 60.02'

N15°09'53"W  
163.00'

N15°09'53"W 63.02'