


CORNER RECORD

Document Number

20140018

City of _____

County of PLACER, CaliforniaBrief Legal Description LOT 38, CHAMBERLANDS UNIT A SUBDIVISION, F/MAPS/33 O.R.P.C.

SEC. 7
T. 14 N.
R. 17 E.
M.D.B. & M.

CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 4/4/2014

COORDINATES (OPTIONAL)

N. _____
 E. _____
Zone _____ Datum _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

BOOK 16 CORNER RECORDS PAGE 96

CORNER- Left as Found Found and Tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

USED RECORD DIMENSIONS AND FOUND MONUMENTS PER F/MAPS/33 O.R.P.C., AND FOUND MONUMENTS OF NO RECORD IN RECORD POSITION, TO REESTABLISH THE MISSING CORNER OF LOT 33, AS SHOWN ON THE ACCOMPANYING PLAT.

A description of the physical condition of the monument as found and as set or reset:

- SET 5/8" REBAR WITH YELLOW PLASTIC CAP LS-7429
- FOUND MONUMENT AS SHOWN ON PLAT
- DIMENSION POINT (NOTHING FOUND OR SET)

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the

Land Surveyors Act on April 09, 2014

Signed [Signature] P.L.S. or R.C.E. No. 7429



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____

and examined and filed May 27, 2014

Signed [Signature] P.L.S. or R.C.E. No. 6584

Title County Surveyor




COUNTY SURVEYOR'S COMMENT:


PLAT OF SURVEY

LOT 38, CHAMBERLANDS UNIT A SUBDIVISION, AS FILED BOOK F OF MAPS AT PAGE 33, OFFICIAL RECORDS PLACER COUNTY, CALIFORNIA. A PORTION OF SECTION 7, TOWNSHIP 14 N., RANGE 17 E., M.D.B. & M.

SCALE 1" = 40' DATE OF SURVEY 4/4/2014



BOOK 16 CORNER RECORDS PAGE 96



CHAMBERLAND DRIVE
(60' R.O.W., CO.RD.# W3003)

- FOUND 1/2" REBAR PER F/MAPS/33 (UNLESS OTHERWISE NOTED)
- DIMENSION POINT (NOTHING FOUND OR SET)
- SET 5/8" REBAR WITH YELLOW PLASTIC CAP L.S. 7429

J/N 2008.00