


**CORNER RECORD**

Document Number 20130019

City of UNINCORPORATED AREA

County of PLACER, California

Brief Legal Description LOT 4 BLOCK "E" ICE LAKES SUBDIVISION UNIT # 2  
BOOK 9 OF MAPS PAGE 1 P.C.R.



SEC. 27  
T. 17 N.  
R. 14 E.  
M.D.M.

**CORNER TYPE**

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey 8/22/12

**COORDINATES (Optional)**

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

- = FOUND BATHEY MONUMENT (T-BAR) w/ NAIL & TAG L.S. 5549
- = FOUND 1/2" REBAR, NO TAG
- ⊗ = FOUND RAILROAD SPIKE, NO TAG PER BK 11 CL 59
- ▲ = FOUND 1/2" REBAR w/ PLAS. CAP R.C.E. 19396 NO RECORD

A description of the physical condition of the monument as found and as set or reset:

- = SET BATHEY MONUMENT (T-BAR) w/ NAIL & TAG L.S. 5549
- ⊗ = SET NAIL & TAG L.S. 5549 ON 3' DIAMETER BOULDER, FLUSH w/ GROUND

JN: 12051

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on AUGUST 27 2012

Signed [Signature] P.L.S or R.C.E. No. L.S. 5549  
EXP. 6/30/13

**COUNTY SURVEYOR'S STATEMENT**



This Corner Record was received \_\_\_\_\_

and examined and filed SEPTEMBER 16, 2013

Signed [Signature] P.L.S or B.C.E. No. 6584

Title Deputy County Surveyor

County Surveyor's Comment \_\_\_\_\_



BOOK 16 CORNER RECORDS, PAGE 45

NOTE: THE BEARINGS AND DISTANCES SHOWN ARE RECORD INFORMATION PER G/MAPS/1 P.C.R.  
 NO MATERIAL DISCREPANCIES WITH RECORD INFORMATION WERE FOUND.

