

# CORNER RECORD

Document Number

20130083


City of \_\_\_\_\_

County of

PLACER

California

Brief Legal Description

LOT 6B, BLOCK 27, RESUBDIVISION OF TAHOE PINES SUBDIVISION, D/MAPS/37 O.R.P.C.

SEC. 36  
T. 15 N.  
R. 16 E.  
M.D.B. & M.

## CORNER TYPE

Government Corner  Control  
Meander  Property  
Rancho  Other  
Date of Survey 9/20/2013

## COORDINATES (OPTIONAL)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
Zone \_\_\_\_\_ Datum \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

**CORNER-** Left as Found  Found and Tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

USED RECORD DIMENSIONS PER D/MAPS/37 O.R.P.C. AND FOUND MONUMENTS OF NO RECORD, AND BK. 9 CR 90 TO REESTABLISH THE MISSING CORNERS OF LOT 6B, BLOCK 27, AS SHOWN ON THE ACCOMPANYING PLAT.

A description of the physical condition of the monument as found and as set or reset:

- SET 5/8" REBAR WITH YELLOW PLASTIC CAP LS-7429  
 FOUND MONUMENT AS SHOWN ON PLAT  
 DIMENSION POINT (NOTHING FOUND OR SET)

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the

Land Surveyors Act on

September 20, 2013

Signed

P.L.S. or R.C.E. No. 7429

## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received \_\_\_\_\_

and examined and filed November 22, 2013

Signed

P.L.S. or R.C.E. No. 6584

Title

Deputy County Surveyor

COUNTY SURVEYOR'S COMMENT:

---

---

---

---

---

---

---

---

