

# CORNER RECORD

Agency Index Bk. 20 Pg 82


Document Number 20180069

City of Rocklin County of Placer, California

Brief Legal Description Radius point at centerline of Cone Court, N Maps 1

### CORNER TYPE

### COORDINATES (Optional)



- Government Corner
- Meander
- Rancho
- Control
- Property
- Other

N. \_\_\_\_\_ E. \_\_\_\_\_

Elevation \_\_\_\_\_

Units  Metric  U.S. Survey Foot

Horizontal Datum \_\_\_\_\_

Zone \_\_\_\_\_ Epoch Date \_\_\_\_\_

Vertical Datum \_\_\_\_\_

Complies with Public Resources Code §§8801-8819

Complies with Public Resources Code §§8890-8902

Date of Survey June 21, 2018

SEC 30, T.11N., R.7.E.

PLS Act Ref.:  8765(d)  8771  8773  Other:

Corner/Monument:  Left as found  Established  Rebuilt  Pre-Construction

Found and tagged  Reestablished  Referenced  Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

See sheet #2 for description(s):

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on July 3, 2018

Signed [Signature] P.L.S. or R.C.E. No. 6947



### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received \_\_\_\_\_

and examined and filed July 11, 2018


Signed [Signature] P.L.S. or R.C.E. No. 6584

Title County Surveyor

County Surveyor's Comment



BOOK 20 CORNER RECORDS, PAGE 82




**LEGEND**

- X - - - SET CUT CROSS IN SIDEWALK AS REFERENCE POINT
- ⊗ - - - FOUND 3/4" IRON PIPE WITH DILAPIDATED PLASTIC CAP (NO RECORD); AFTER RE-PAVING SET RAILROAD SPIKE "LS 6947"
- - - - FOUND 3/4" IRON PIPE WITH DILAPIDATED PLASTIC CAP (NO RECORD)
- (1) - - - RECORD DATA PER N MAPS 1

**CenterPoint Engineering, Inc.**

Civil Engineering & Land Surveying

1217 Pleasant Grove Blvd. Suite 130 · Roseville, CA · 95678  
 Phone: 916-773-4006 Fax: 916-773-4498



DRAWN BY: BB

CHECKED BY: MH

SHEET: 2 OF 2

SCALE: 1" = 40'

DATE: 7-3-2018