


CORNER RECORD

Document Number _____

City of _____

County of Placer, California

Brief Legal Description Lot 144, Alpine Meadows Estates Sub'd Unit #4, H/Maps/56



T15N

R16E

CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 6-06-03

COORDINATES (Optional)

N. _____
E. _____
Zone NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
See sketch on back.

Found 1/2" rebar in record position at most Northerly corner of Lot 144, Alpine Meadows Estates, H/Maps/56.

Found 3/4" rebar at Southwest corner of Lot 143 in record position.

A description of the physical condition of the monument as found and as set or reset:
See sketch on back.

Set concrete nail in rock tagged LS 6819 in record location.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on June 30th, 2003

Signed Keith Masuda P.L.S. or R.C.E. No. 6819



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received APRIL 11, 05

and examined and filed, APRIL 26 2005

Signed Charles B. Grant P.L.S. or R.C.E. No. LS 6158

Title, DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____




BOOK 9 CORNER RECORDS PAGE 67

PLAT OF SURVEY

LOT 144 OF ALPINE MEADOWS ESTATES SUBDIVISION UNIT #4, H/MAPS/56,
P.C.R., SECTION 4, TOWNSHIP 15 NORTH, RANGE 16 EAST, M.D.M.

COUNTY OF PLACER
SCALE: 1" = 40'

CALIFORNIA
JUNE 30, 2003



○ SET CONC. NAIL IN ROCK TAGGED LS6819

● FOUND MONUMENTS AS NOTED

○ DIMENSION POINT (NOTHING FOUND OR SET)

ALL DIMENSIONS ARE PER H/MAPS/56
NO MATERIAL DISCREPANCY WAS FOUND PER SAID MAP