

CORNER RECORD

Document Number _____

City of _____

County of Placer, California

Brief Legal Description Lot 69, Tahoe Woods Unit #1, I/Maps/30



CORNER TYPE

T15N Government Corner Control
 Meander Property
 R16E Rancho Other
 Date of Survey 11-08-04

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
 See sketch on back.

Found 1/2" rebar in record position at most Northerly corner of Lot 69, Tahoe Woods, I/Maps/30. Found 3/4" rebar at most Easterly corner of Lot 69 in record position.

A description of the physical condition of the monument as found and as set or reset:
 See sketch on back.

Set 5/8" rebar tagged LS 6819 in record location.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on December 20th, 2004

Signed [Signature] P.L.S. or R.C.E. No. 6819



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received APRIL 28 2005

and examined and filed, MAY 3 2005

Signed [Signature] P.L.S. or R.C.E. No. LS 6158

Title, DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____



BOOK 9 CORNER RECORDS PAGE 66

