


CORNER RECORD

COUNTY OF PLACER, CALIFORNIA

City of \_\_\_\_\_ Document Number \_\_\_\_\_

Brief Legal Description Lot 60, Serene Lakes Unit No. 1 Book "I" of Maps, Page 17



T.17N.,R.17E.

CORNER TYPE

COORDINATES (Optional)

Government Corner  Control  N. \_\_\_\_\_  
 Meander  Property  E. \_\_\_\_\_  
 Rancho  Other  Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Date of Survey August, 2004 Elev. \_\_\_\_\_

Corner— Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner:

● ~ found 1/2" iron pin as per (R1)

A description of the physical condition of the monument as found and as set or reset:

∅ ~ set 5/8" rebar with 2" aluminum cap stamped "TAHOE BASIN LAND SURVEYING, THOMAS C. BUSWELL, LS 5886"

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land

Surveyor's Act on JANUARY 3RD, 20 05

Signed Thomas C. Buswell L.S. or R.C.E. Number 5886



COUNTY SURVEYOR'S STATEMENT

This Corner Record was Received MAY 2 2005 and Examined

and filed MAY 3 2005


Signed Charles B. Grant Title DEPUTY COUNTY SURVEYOR  
LS 6158

County Surveyor's Comment \_\_\_\_\_




BOOK 9 CORNER RECORDS PAGE 69


Lot 58



Lot 59





Lot 60



Hillary Drive  
50' r.o.w.



scale 1" = 40'



fd. 1/2" iron pin (R1)  
typical

Lot 61

Lot 62



(C) ~ calculated from Record

(R1) ~ record as per Book "I" Maps, Page 17

o ~ dimension point only

⊗ ~ set 5/8" bar with 2" aluminum cap stamped "TAHOE BASIN LAND SURVEYING, THOMAS C. BUSWELL, LS 5886"

BASIS OF BEARINGS