


**CORNER RECORD**

Document Number \_\_\_\_\_

City of AUBURN

County of PLACER, California

Brief Legal Description P1 "B" 24-PM-127 Pt 1 SE 1/4 SEC 10 T12N R8E M.D.M.



**CORNER TYPE**

- Government Corner  Control
- Meander  Property
- Rancho  Other
- Date of Survey 6-12-04

**COORDINATES (Optional)**

- N. \_\_\_\_\_
- E. \_\_\_\_\_
- Zone \_\_\_\_\_ NAD27  NAD83
- NAD83 Epoch \_\_\_\_\_
- Elev. \_\_\_\_\_
- Vert. Datum: NGVD29  NAVD88
- Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

I FOUND 4 MONUMENTS FROM 24-PM-127 WHICH ARE CONSISTENT RELATIVE TO EACH OTHER ALTHOUGH 2 ARE RR SPIKES INSTEAD OF 1/2" REBAR

A description of the physical condition of the monument as found and as set or reset:

RESET MISSING MONTS W/ 3/4" REBAR W/ PLASTIC CAP STAMPED RLB 29265 IN RECORD POSITION

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on 6-15-04

Signed R.G. Hillman P.L.S or R.C.E. No. 29265



**COUNTY SURVEYOR'S STATEMENT**


This Corner Record was received AUGUST 19, 2004

and examined and filed SEPTEMBER 1 2004

Signed Charles B. Grant P.L.S or R.C.E. No. LS 6158

Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment \_\_\_\_\_



BOOK 9 CORNER RECORDS PG 22

FND 5" PIPE  
2" DIAM

S00°1'E 104.48'

S40°10'E 165.00'

S88°50'E 82.00'

AEOLIA DRIVE

N75°54'E 36.94'

S65°10'E 50.00'

S09°14'W 15.57'

N75°54'E 32.54'

S65°10'E 57.64'

S65°10'E 9.18'

FND 1/2" REBAR

FND. RR SPIRE

RCE 14803

PARCEL A  
24 PM 127

PARCEL B  
24-PM-127

ROSENE  
96-75488

- NOTHING FND. NOTHING SET
- FND. AS DESCRIBED
- ⊙ RESET MISSING MON'T W/  
3/4" REBAR W/ PLASTIC CAP  
STAMPED RCE 29265

S05°46'45"W 76.01'

S77°49'E 56.84'

SMITH  
99-19291

N80°46'W 8.79'

S05°14'W 126.21'

S12°9'E 121.605



BH 9 PG 22