

Corner Record

County of Placer, California

City of _____

Document Number _____

Brief Legal Description

LOT 15 of CAROLINDA RANCH ESTATES (K MAPS 10)

SECTION 34
T. 11 N. R. 7 E.

Corner Type

Government Corner Control
Meander Property
Rancho Other
Date of Survey 10/05/04

Coordinates

(Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner- Left as Found Found and Tagged Established Reestablished Rebuilt

Identification and Type of Corner Found, Evidence used to Identify or Procedure used to Establish or Reestablish the corner:

FOUND 1/2" REBAR & CAP RCE 9093 @ THE NORTHEAST & SOUTHEAST CORNER S.

A Description of the Physical Condition of the Monument as Found and as Set or Reset:


SET 5/8" REBAR & CAP LS 6718 @ THE NORTHWEST CORNERS AND A PK & WASHER
LS 6718 @ THE SOUTHWEST CORNER.

Surveyor's Statement

This Corner Record was prepared by me or under my direction in conformance with

The Land Surveyor's Act on 12/07/04.

Signed Kevin Burgess L.S. 6718




County Surveyor's Statement

This Corner Record was received _____, 2004 and

examined and filed 12-16, 2004

Signed Charles B. Grant
LS 6158

Title DEPUTY COUNTY SURVEYOR




County Surveyor's Comment:

BOOK 9 CORNER RECORDS PAGE 35

LEGEND

- SET 5/8" REBAR & CAP LS 6718
- ⊗ SET PK NAIL & WASHER LS 6718
- FOUND 1/2" REBAR & CAP RCE 9093 PER K MAPS 10
- () RECORD DATA PER K MAPS 10



SCALE
1" = 100'

BOOK L OF MAPS PAGE 10